



Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back SEL**

Color: **Gray**

Mileage: **77,121
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC75LC4KU114554**

Work Order/
Stock Number: **46331687**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G131100W**

Vehicle Grade : **Grade 3.9**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Power - Driver Only	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

LF Tires - 7/32 inch

LR Tires - 8/32 inch

RF Tires - 7/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - HANKOOK

Tire Brand - Front Right - HANKOOK

Tire Brand - Rear Left - BLACKHAWK

Tire Brand - Rear Right - BLACKHAWK

Tire Model - RR - Street-H HH11

Tire Model - RF - Kinergy ST (H735)

Tire Model - LR - Street-H HH11

Tire Model - LF - Kinergy ST (H735)

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Curb Rash	-	1 To 2 Inches
	Left Rear Wheel Cover	Curb Rash	-	2 To 3 Inches
	Grille	Multiple Scratches Light	-	3
	Front Bumper	Cracked	-	1 To 2 Inches
	Rear Bumper	Chipped	-	1
	Hood	Chipped	-	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.