



Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **Silver**

Mileage: **27,398
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPD74LF7LH617911**

Work Order/
Stock Number: **46331813**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G13A4213**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15
Car Tire Size - LR 195 / 65 R 15	LF Tires - 9/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - LAUFENN
Tire Brand - Front Right - NEXEN	Tire Brand - Rear Left - NEXEN	Tire Brand - Rear Right - NEXEN
Tire Model - LF - G Fit As (LH41)	Tire Model - LR - Npriz AH8	Tire Model - RF - Npriz AH8
Tire Model - RR - Npriz AH8		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Multiple Scratches Light	-	5

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Scuffed	-	6 To 7 Inches
	Right Front Wheel Cover	Curb Rash	-	9 To 10 Inches
	Right Front Door	Multiple Scratches Heavy	-	2
	Hood	Chipped	-	5
	Front Bumper	Chipped	-	4
	Right Rear Wheel Cover	Curb Rash	-	6 To 7 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	6
	Deck Lid	Multiple Scratches Heavy	-	3
	Left Rear Wheel Cover	Curb Rash	-	5 To 6 Inches
	Roof	Chipped	-	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.