



Approved CR

IAA Sioux Falls
47028 276th St
Branch No 362
Sioux Falls, SD 57104
(605)271-8855/(605)271-4662
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 FORD
BRONCO
SPORT**

Bodystyle/Series: **Sport Utility
Vehicle -**

Color: **Silver**

Mileage: **79,810
(Verified)**

Turn-in Mileage: **-**

VIN: **3FMCR9A68PRD58155**

Work Order/
Stock Number: **45839279**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G61A1334**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	3-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

LF Tires - 7/32 inch

LR Tires - 5/32 inch

RF Tires - 7/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - LF - Crugen HP71

Tire Model - LR - Crugen HP71

Tire Model - RF - Crugen HP71

Tire Model - RR - Crugen HP71

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Chipped	-	2
	Left Front Wheel	Curb Rash	-	3 To 4 Inches
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Rear Door	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.