



Approved
CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE
DURANGO**
Sport Utility Vehicle
Bodystyle/Series: **SPECIAL SERVICE
AWD**
Color: **Gray**
Mileage: **63,034 (Verified)**
Turn-in Mileage: -
VIN: **1C4SDJFT1JC383807**
Work Order/
Stock Number: **46357634**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G621219V**
Vehicle Grade : **Grade 4.1**
Remarks: -
Announcements: **• ANNOUNCEMENTS:**
Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 60 R 18

Car Tire Size - RF 265 / 60 R 18

Car Tire Size - LF 265 / 60 R 18

Car Tire Size - LR 265 / 60 R 18

LF Tires - 7/32 inch

LR Tires - 10/32 inch

RF Tires - 7/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - IRONMAN

Tire Brand - Front Right - IRONMAN

Tire Brand - Rear Left - IRONMAN

Tire Brand - Rear Right - IRONMAN

Tire Model - RR - All Country HT


Tire Model - RF - All Country HT

Tire Model - LR - All Country HT

Tire Model - LF - All Country HT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	10 Or More
	Rear Bumper	Heavy Scratch	-	1/8 To 1/2 Inch
	Right Qtr Panel	Light Scratch	-	7 To 8 Inches
	Right Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.