Approved CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 FORD C-MAX HYBRID**
Bodystyle/Series:	**4 Door Hatch Back SE**
Color:	**Silver**
Mileage:	**24,045 (Verified)**
Turn-in Mileage:	-
VIN:	**1FADP5AU2JL102076**
Work Order/ Stock Number:	**46460885**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G13A4035**
Vehicle Grade :	**Grade 4.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 50 R 1	Car Tire Size - RF 225 / 50 R 1	Car Tire Size - LF 225 / 50 R 17
Car Tire Size - LR 225 / 50 R 1	LF Tires - 10/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - SAILUN
Tire Brand - Front Right - SAILUN	Tire Brand - Rear Left - SAILUN	Tire Brand - Rear Right - SAILUN
Tire Model - LF - Atrezzo SH408	Tire Model - LR - Atrezzo SH408	Tire Model - RF - Atrezzo SH408
Tire Model - RR - Atrezzo SH408		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	-	8

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Rear Wheel	Curb Rash	-	< 1/8 Inch
	Front Bumper	Misaligned	-	Repair Required
	Right Front Door	Chipped	-	1

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.