Approved CR

America`s Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD F-150**
Bodystyle/Series:	**4 Door Vehicle XL SUPERCREW 4WD**
Color:	**WHITE**
Mileage:	**72,756 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FTEW1EB9LKD26473**
Work Order/ Stock Number:	**000356102**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**LATES)**
Vehicle Grade :	**Grade 2.1**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

4 Wheel Drive	4 Wheel Drive	4th Passenger Door
ABS Brakes	Air Conditioning	Automatic Headlights
Auxiliary Pwr Outlet	Bench Seating	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size P265/70SR17	Car Tire Size - LR tire size P265/70SR17
Car Tire Size - LF tire size P265/70SR17	Car Tire Size - RR tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Empty Weight - 4770 lb	Engine Immobilizer
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 9/32 inch	LR Tires - 9/32 inch	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass. Air Bag	Power Brakes
Power Folding Mirrors	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 8/32 inch	RR Tires - 9/32 inch	Rear Defrost
Reverse Camera	Running Board	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Firestone
Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown






Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Headlining	Stained	Report	Permanent
	Hood	Multiple Dents/Paint Damage	Report	5
	Left Bed Side	Chipped	Report	5
	Left Front Door	Multiple Dents/No Paint Damage	Report	4
	Left Front Fender	Multiple Dents/Paint Damage	Report	4
	Left Rear Door	Multiple Scratches Light	Report	6
	Right Bed Side	Multiple Scratches Light	Report	6
	Right Front Door	Multiple Scratches Light	Report	6

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Multiple Scratches Light	Report	6
	Right Rear Door	Peeling	Report	2 To 3 Inches
	Tailgate	Multiple Scratches Light	Report	6
[no photo]	4 Wheel Drive	Vibration	Report	Repair Required
[no photo]	Oil	Low Fluid	Report	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.