



Approved CR

IAA Billings
75 Cerise Road
Branch No 361
Billings, MT 59101
(406) 259-2377/(406) 259-2302
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 RAM
1500
CLASSIC**
-
Bodystyle/Series: **TRADESMAN
4X4 6'4 BOX**
Color: **White**
Mileage: **55,274
(Verified)**
Turn-in Mileage: -
VIN: **1C6RR7FG0KS629542**
Work Order/
Stock Number: **45888983**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G621070W**
Vehicle Grade : **Grade 2.4**
Remarks: -
Announcements:

- CHECK
ENGINE
LIGHT ON,
WINDSHIELD
CRACKED

Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive

Equipment

Seat Count: -

Brakes:

Anti Lock Brakes

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - LR 265 / 70 R 17

LF Tires - 8/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - KANATI

Tire Brand - Front Right - KANATI

Tire Brand - Rear Left - KANATI

Tire Brand - Rear Right - KANATI

Tire Model - RR - Armor Hog Atx

Tire Model - RF - Armor Hog Atx

Tire Model - LR - Armor Hog Atx

Tire Model - LF - Armor Hog Atx

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Bed Side	Chipped	-	2
	Right Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	-	4
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Overall Vehicle	De-Identify	-	Removal Required
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Rocker Panel	Scraped	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Windshield	Cracked	-	> 12 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Front Metal Bumper Painted	Chipped	-	2
	Grille	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.