



Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 RAM
1500**
Bodystyle/Series: **2 Door Pickup
Truck ST**
Color: **WHITE**
Mileage: **43,230
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **3C6JR7AG7HG585219**
Work Order/
Stock Number: **000311933**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G62-4746S**
Vehicle Grade : **Grade 4.0**
Remarks: **-**

Announcements:

• DEFICIENCIES,
WHEN
KNOWN, HAVE
BEEN NOTED
IN THE ITEM
DESCRIPTION;
HOWEVER,
• THE ABSENCE
OF ANY
INDICATED
DEFICIENCIES
DOES NOT
MEAN THERE
ARE NONE

Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	No

Equipment

Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Additional Equipment:

4 Wheel Drive	Air Conditioning	LF Tires - 16/32 inch
LR Tires - 10/32 inch	Power Brakes	Power Steering
RF Tires - 15/32 inch	RR Tires - 8/32 inch	Security System
Tilt Wheel	Tire Brand - Front Left - LF TIRE MFG Goodyear	Tire Brand - Front Right - RF TIRE MFG Goodyear
Tire Brand - Rear Left - LR TIRE MFG Goodyear	Tire Brand - Rear Right - RR TIRE MFG Goodyear	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Rear Bumper	Rust	Report	Permanent
	Vin Plate	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Front	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.