



Approved CR

IAA Minneapolis/St. Paul
1280 Jackson Street
Branch No 526
St. Paul, MN 55117
(651) 488-0581/(651) 488-3644
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
SILVERADO
3500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **White**

Mileage: **14,479
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC4KYCG2HF190119**

Work Order/
Stock Number: **46384558**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631400U**

Vehicle Grade : **Grade 3.9**

Remarks: **-**

Announcements:

**• WHEEL
CORROSION**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 18

Car Tire Size - RF 265 / 70 R 18

Car Tire Size - LF 265 / 70 R 18

Car Tire Size - LR 265 / 70 R 18

LF Tires - 13/32 inch

LR Tires - 13/32 inch

RF Tires - 13/32 inch

RR Tires - 14/32 inch

Tire Brand - Front Left - COOPER

Tire Brand - Front Right - COOPER

Tire Brand - Rear Left - COOPER

Tire Brand - Rear Right - COOPER

Tire Model - LF - Discoverer HT3

Tire Model - LR - Discoverer HT3

Tire Model - RF - Discoverer HT3

Tire Model - RR - Discoverer HT3

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Running Board	Aftermarket	-	Acceptable
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Tonneau Cover	Aftermarket	-	Acceptable
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Multiple Dents/No Paint Damage	-	2
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Left Rear Wheel	Corrosion	-	1/2 To 1 Inch
	Tailgate	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH

WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS
CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.