



Approved CR

IAA Miami-North  
20499 Stirling Road  
Branch No 736  
Southwest Ranch, FL 33332  
(954)680-4370/(954)680-4372  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024  
SUBARU  
LEGACY**

Bodystyle/Series: **4 Door Sedan**

Color: **Silver**

Mileage: **24,188  
(Verified)**

Turn-in Mileage: **-**

VIN: **4S3BWAB68R3028266**

Work Order/  
Stock Number: **46384560**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G10A0517**

Vehicle Grade : **Grade 0.8**

Remarks: **-**

Announcements: **• Salvage**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                                           |                 |                         |
|------------------------|-------------------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Continuously Variable Transmission</b> | A/C:            | <b>No</b>               |
| Engine:                | <b>4-Cylinder Gas</b>                     | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>2.5 L</b>                              | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>                           | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | <b>-</b>                                  | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>              | Rear Defroster: | <b>Yes</b>              |
| Airbag:                | <b>-</b>                                  | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | <b>3rd</b>                                | Drive Type:     | <b>All Wheel Drive</b>  |
| Seat Count:            | <b>-</b>                                  | Brakes:         | <b>Anti Lock Brakes</b> |

## Equipment

### Additional Equipment:

Car Tire Size - LF 228 / 55 R 17

Car Tire Size - LR 228 / 55 R 17

Car Tire Size - RR 228 / 55 R 17

Car Tire Size - RF 228 / 55 R 17

LF Tires - 7/32 inch

LR Tires - 8/32 inch

RF Tires - 7/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - RR - Avid GT S35

Tire Model - RF - Avid GT S35

Tire Model - LR - Avid GT S35

Tire Model - LF - Avid GT S35

## Non Chargeable Damages

| Photo                                                                               | Item                       | Damage | Action | Severity             |
|-------------------------------------------------------------------------------------|----------------------------|--------|--------|----------------------|
|    | Right Apron                | Broken | -      | Replacement Required |
|   | Warning - Traction Control | On     | -      | Unacceptable         |
|  | Warning Light - Air Bag    | On     | -      | Unacceptable         |
|  | Warning Light - Abs        | On     | -      | Unacceptable         |
|  | Warning Light - Engine     | On     | -      | Unacceptable         |

| Non Chargeable Damages                                                              |                        |            |        |          |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
| Photo                                                                               | Item                   | Damage     | Action | Severity |
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Engine                 | Photo Only | -      | -        |
|    | Keys                   | Photo Only | -      | -        |
|    | Front Cover Center     | Photo Only | -      | -        |
|    | Right Side Panel       | Photo Only | -      | -        |
|   | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |
|  | Extra Photo 2          | Photo Only | -      | -        |
|  | Extra Photo 3          | Photo Only | -      | -        |
|  | Right Front Fender     | Photo Only | -      | -        |

| Non Chargeable Damages                                                              |                         |            |        |                      |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------------------|
| Photo                                                                               | Item                    | Damage     | Action | Severity             |
|    | Extra Photo 4           | Photo Only | -      | -                    |
|    | Extra Photo 5           | Photo Only | -      | -                    |
|    | Extra Photo 6           | Photo Only | -      | -                    |
|    | Extra Photo 7           | Photo Only | -      | -                    |
|    | Left Front Fender       | Photo Only | -      | -                    |
|   | Left Rear Bumper/Cover  | Photo Only | -      | -                    |
|  | Right Rear Bumper/Cover | Photo Only | -      | -                    |
|  | Core Support            | Broken     | -      | Replacement Required |
|  | Photo - Dash            | Photo Only | -      | -                    |
|  | Extra Photo 1           | Photo Only | -      | -                    |

### Non Chargeable Damages

| Photo                                                                             | Item       | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|------------|------------|--------|----------|
|  | Odometer   | Photo Only | -      | -        |
|  | Rear Seats | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item                       | Damage        | Action | Severity             |
|-------------------------------------------------------------------------------------|----------------------------|---------------|--------|----------------------|
|    | Front Bumper Reinforcement | Broken        | -      | Replacement Required |
|   | Hood                       | Severe Damage | -      | Replacement Required |
|  | Right Front Fender         | Severe Damage | -      | Replacement Required |
|  | Right Front Wheel          | Curb Rash     | -      | 1 To 2 Inches        |
|  | Left Head Lamp             | Misaligned    | -      | Repair Required      |

| Chargeable Damages                                                                 |                     |          |        |                      |
|------------------------------------------------------------------------------------|---------------------|----------|--------|----------------------|
| Photo                                                                              | Item                | Damage   | Action | Severity             |
|   | Airbag - Front Left | Deployed | -      | Replacement Required |
|   | Front Bumper        | Broken   | -      | Replacement Required |
|   | Grille              | Broken   | -      | Replacement Required |
|  | Right Head Lamp     | Missing  | -      | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.