Approved
CR

IAA Fontana
9951 Banana Ave
Branch No 132
Fontana, CA 92335
(909)355-9400/(909)822-9311
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2021 SUBARU ASCENT**
Bodystyle/Series:	**Sport Utility Vehicle PREMIUM**
Color:	**Gray**
Mileage:	**98,214 (Verified)**
Turn-in Mileage:	-
VIN:	**4S4WMABD9M3461430**
Work Order/ Stock Number:	**46457848**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G621170Y**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	• SEE IAA CONDITION REPORT FOR MORE INFORMATION.
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment


Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - LR 245 / 60 R 18	Car Tire Size - LF 245 / 60 R 18	Car Tire Size - RR 245 / 60 R 18
Car Tire Size - RF 245 / 60 R 18	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 4/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - LAUFENN
Tire Brand - Front Right - LAUFENN	Tire Brand - Rear Left - LAUFENN	Tire Brand - Rear Right - LAUFENN
Tire Model - RR - X Fit HT (LD01)	Tire Model - RF - X Fit HT (LD01)	Tire Model - LR - X Fit HT (LD01)
Tire Model - LF - X Fit HT (LD01)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Windshield	Star In Glass	-	1 To 2 Inches
	Right Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Door	Heavy Scratch	-	9 To 10 Inches
	Right Front Mirror Housing	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Rear Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.