Approved CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 RAM 1500**
Bodystyle/Series:	- -
Color:	**White**
Mileage:	**50,268 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7FGXGS396048**
Work Order/ Stock Number:	**46456526**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G623660S**
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - ELDORADO
Tire Brand - Front Right - ELDORADO	Tire Brand - Rear Left - ELDORADO	Tire Brand - Rear Right - ELDORADO
Tire Model - LF - Sport Fury AT4S	Tire Model - LR - Sport Fury AT4S	Tire Model - RF - Sport Fury AT4S
Tire Model - RR - Sport Fury AT4S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Right Front Door	Multiple Scratches Heavy	-	3
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Rear Door	Chipped	-	5
	Right Bed Side	Chipped	-	6
	Right Rear Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	7 To 8 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Bed Side	Multiple Scratches Heavy	-	3
	Left Rear Wheel	Corrosion	-	8 To 9 Inches
	Left Rear Door	Chipped	-	2
	Left Front Door	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rocker Panel	Chipped	-	3
	Left Front Fender	Chipped	-	4
	Left Front Wheel	Corrosion	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.