



Approved CR

Central Auto Auction
185 Welton St.
Hamden, CT 06517
203-787-2277/203-787-6564
elise@centralaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
2500**
Bodystyle/Series: **4 Door
Pickup Truck**
Color: **BLUE**
Mileage: **18,625
(Verified)**
Turn-in Mileage: **-**
VIN: **3C6TR5HT0GG310757**
Work Order/
Stock Number: **0171673**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **630755S**
Vehicle Grade : **Grade 3.6**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	-	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	6	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	Car LF Tires - 6/32 inch	Car LR Tires - 6/32 inch
Car RF Tires - 6/32 inch	Car RR Tires - 6/32 inch	Cylinders - 8
Ignition Key - 2key(s)	LF Tires - 6/32 inch	LR Tires - 6/32 inch
Misc. Special Features - Key - Ignition	Navigation System	Power Mirrors
RF Tires - 6/32 inch	RR Tires - 6/32 inch	Steering Wheel Audio Control
Tire LF - 6/32 inch	Tire RF - 6/32 inch	Tire Rating Front Left - GOOD
Tire Rating Front Right - GOOD	Tire Rating Rear Left - GOOD	Tire Rating Rear Right - GOOD
Tow Hitch	Trip Computer	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
[no photo]	Left Front Door	Multiple Scratches Heavy	-	5
	Right Bed Side	Multiple Dents/Paint Damage	-	5
	Tailgate	Dent(S) W/ Paint Dmg	-	6 To 7 Inches
[no photo]	Left Rear Door	Multiple Scratches Heavy	-	5
	Left Bed Side	Multiple Scratches Heavy	-	10 Or More
	Left Front Fender	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.