



Approved CR

Central Auto Auction
185 Welton St.
Hamden, CT 06517
203-787-2277/203-787-6564
elise@centralaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 JEEP
GRAND
CHEROKEE**

Bodystyle/Series: **4 Door
Wagon -**

Color: **BLACK**

Mileage: **68,068
(Verified)**

Turn-in Mileage: **-**

VIN: **1C4RJFAG8JC381437**

Work Order/
Stock Number: **0171735**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **621667V**

Vehicle Grade : **Grade 3.5**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	-	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	5	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	Backup camera and monitor	Car LF Tires - 6/32 inch
Car LR Tires - 6/32 inch	Car RF Tires - 6/32 inch	Car RR Tires - 6/32 inch
Cylinders - 6	Fog Lights	Ignition Key - 1key(s)
LF Tires - 6/32 inch	LR Tires - 6/32 inch	Misc. Special Features - Back Up Sensor, Auto Climate Control, Dual Zone Climate Control, Key - Remote, Remote Starter
Parking Distance Control	Power Driver Seat	Power Mirrors
Power Trunk/Liftgate	RF Tires - 6/32 inch	RR Tires - 6/32 inch
Tire LF - 6/32 inch	Tire RF - 6/32 inch	Tire Rating Front Left - GOOD
Tire Rating Front Right - GOOD	Tire Rating Rear Left - GOOD	Tire Rating Rear Right - GOOD
Trip Computer	XM Radio	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Area	Aftermarket	-	Removal Required
	Warning Light - Electrical	On	-	Unacceptable
	Headlining	Aftermarket	-	Removal Required
	Center Console	Aftermarket	-	Removal Required
	Right Front Door Glass	Aftermarket	-	Removal Required
	Right Front Door	Chipped	-	4
	Lift Gate	Aftermarket	-	Removal Required
	Left Rocker Inner	Multiple Dents/No Paint Damage	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Scratches Heavy	-	5
	Left Rocker Inner	Dent(S) W/No Paint Dmg	-	6 To 7 Inches
	Left Mirror	Multiple Scratches Light	-	5
	Left Front Fender Liner	Misaligned	-	Repair Required
	Left Front Fender	Multiple Scratches Light	-	5
	Left Drip Rail	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Left Front Door Glass	Aftermarket	-	Removal Required
	Windshield	Aftermarket	-	Removal Required
	Hood	Corrosion	-	11 To 12 Inches
	Grille	Aftermarket	-	Removal Required
	Front Bumper	Gouged	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.