



Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024 DODGE
DURANGO**
Bodystyle/Series: **Sport Utility
Vehicle
PURSUIT
AWD**
Color: **White**
Mileage: **90,779
(Verified)**
Turn-in Mileage: **-**
VIN: **1C4RDJFG8RC182631**
Work Order/
Stock Number: **46217810**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62B3381**
Vehicle Grade : **Grade 3.1**
Remarks: **-**



Announcements:

• CONDITION
UNKNOWN
• FORMER
POLICE
VEHICLE
• REAR DOORS
/ WINDOWS
INOPERABLE
MAY BE
INOPERABLE
• SALVAGE
STAMPED
CERTIFICATE
TO OBTAIN
TITLE WILL
BE ISSUED

Certification : **-**
Req. Prev. Repair **-**
Order:

Drivable: Yes

Equipment

Transmission: **Automatic Transmission** A/C: **No**

Equipment

Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Disc

Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 3/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - RR - Alenza	Tire Model - RF - Alenza	Tire Model - LR - Eagle Touring
Tire Model - LF - Alenza		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Fog Light Covers	Misaligned	-	Repair Required
	Left Fog Light Covers	Misaligned	-	Repair Required
	Front Bumper	Chipped	-	10 Or More
	Left Front Door	Multiple Dents/Paint Damage	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Vehicle	De-Identify	-	Removal Required
 Tire Information Driver Front Size: 205 / 60 R 16 Brand: MICHELIN Tread Depth: 6/32" Model: Accura Driver Rear Size: 205 / 60 R 16 Brand: MICHELIN Tread Depth: 6/32" Model: Accura Passenger Rear Size: 205 / 60 R 16 Brand: MICHELIN Tread Depth: 6/32" Model: Accura Passenger Front Size: 205 / 60 R 16 Brand: MICHELIN Tread Depth: 6/32" Model: Accura	Right Front Tire	Worn	-	Replacement Required
	Rear Bumper Cover Upper	Chipped	-	1
	Rear Bumper Tow Hook Cover	Bent	-	Replacement Required
	Steering Wheel	Worn	-	Replacement Required
	Right Front Fender	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.