Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 CHEVROLET SILVERADO 1500**
Bodystyle/Series:	**4 Door Vehicle WORK TRUCK DOUBLE CAB 4WD**
Color:	**WHITE**
Mileage:	**89,764 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1GCRYAEK5LZ326831**
Work Order/ Stock Number:	**000115953**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 3.5**
AutoGrade :	**3.5 - Average**
Remarks:	-
Announcements:	• ** GREEN LIGHT
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**2.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**

Equipment

Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**


Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Auxiliary Pwr Outlet	Bedliner
Bluetooth Connection	Car Tire Size - LF tire size 265/70R17	Car Tire Size - LR tire size 265/70R17
Car Tire Size - RR tire size 265/70R17	Car Tire Size - RF tire size 265/70R17	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Floor Mats	Heated Mirrors	Keyless Entry
LF Tires - 14/32 inch	LR Tires - 14/32 inch	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
RF Tires - 14/32 inch	RR Tires - 13/32 inch	Reverse Camera
Seat Trim - Cloth	Side Airbags - Front	Stereo - AM/FM Radio
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Goodyear
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Goodyear
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission	Turbocharged	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	Touch Up	2
	Right Bed Side	Multiple Dents/No Paint Damage	PDR	Pdr-2 Dents
	Right Bed Side	Chipped	Touch Up	6
	Left Rear Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Front Fender	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Front Door	Chipped	Touch Up	3
	Left Rocker Panel	Multiple Dents/No Paint Damage	PDR	10 Or More
	Left Bed Side	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Bed Side	Chipped	Touch Up	6
	Hood	Chipped	Touch Up	8
	Right Rocker Panel	Multiple Dents/No Paint Damage	PDR	Pdr-5 Dents
	Rear Metal Bumper Painted	Multiple Scratches Heavy	Touch Up	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Right Bumper/Cover	Chipped	Touch Up	5
	Right Front Fender	Chipped	Touch Up	3
	Right Front Fender	Multiple Dents/No Paint Damage	PDR	10 Or More
	Tailgate	Dent(S) W/ Paint Dmg	Repair	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.