



Approved CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-450**
Bodystyle/Series: **4 Door
Vehicle XL**
Color: **BLUE**
Mileage: **89,057
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1FT8W4DT6GEC64155**
Work Order/
Stock Number: **000594586**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **710278S**
Vehicle Grade : **Grade 2.6**
AutoGrade : **2.6 - Below
Average**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel Turbo	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	4th Passenger Door
ABS Brakes	Auxiliary Pwr Outlet	Bench Seating
Bluetooth Connection	Brake Assist System	CD Player
Car Tire Size - LF tire size LT225/70SR19.5	Car Tire Size - LR tire size LT225/70SR19.5	Car Tire Size - RF tire size LT225/70SR19.5
Car Tire Size - RR tire size LT225/70SR19.5	Child Safety Locks	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Dual Rear Wheels
Empty Weight - 8611 lb	Engine Immobilizer	Heated Mirrors
Intermittent Wipers	Keyless Entry	LF Tires - 10/32 inch
LR Tires - 10/32 inch	MP3 Radio	Master Key - 1key(s)
Motor Fuel Type - Diesel	Pass. Air Bag	Power Brakes
Power Folding Mirrors	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Running Board
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - LF tire mfg Other	Tire Brand - Front Right - RF tire mfg Other	Tire Brand - Rear Left - LR tire mfg Other
Tire Brand - Rear Right - RR tire mfg Other	Tow Hitch	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Turbocharged	Turn Signal Mirrors
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Scratches Heavy	Repair	8
	Right Bed Side	Multiple Dents/Paint Damage	Repair	4
	Right Bed Side	Multiple Scratches Heavy	Repair	8
	Right Front Door	Multiple Scratches Heavy	Repair	8
	Right Rear Door	Multiple Scratches Heavy	Repair	6
[no photo]	Tailgate	Multiple Dents/Paint Damage	Repair	8
[no photo]	Hood	Multiple Scratches Heavy	Repair	8
[no photo]	Left Bed Side	Multiple Scratches Heavy	Repair	8
[no photo]	Left Front Fender	Multiple Scratches Heavy	Repair	5
[no photo]	Rear Bumper	Multiple Dents/No Paint Damage	Repair	7
[no photo]	Tailgate	Multiple Scratches Heavy	Repair	8
	Left Front Door	Multiple Scratches Heavy	Repair	6
	Left Rear Door	Dent(S) W/ Paint Dmg	Repair	8 To 9 Inches
[no photo]	Left Front Fender	Dent(S) W/ Paint Dmg	Repair	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.