



Approved CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Gray**

Mileage: **88,052
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG9KR669228**

Work Order/
Stock Number: **46331196**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G410783W**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

LF Tires - 8/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - Calerdera

Tire Brand - Front Right - Calerdera

Tire Brand - Rear Left - Calerdera

Tire Brand - Rear Right - Calerdera

Tire Model - RR - Confidence

Tire Model - RF - Confidence

Tire Model - LR - Confidence

Tire Model - LF - Confidence

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	4
	Right Front Wheel	Corrosion	-	> 12 Inches
	Hood	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Roof	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Curb Rash	-	6 To 7 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Heavy Scratch	-	1/2 To 1 Inch
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel Cover	Curb Rash	-	5 To 6 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Left Qtr Molding	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.