



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
EXPRESS
3500**
Bodystyle/Series: - **LS**
Color: **Silver**
Mileage: **47,756
(Verified)**
Turn-in Mileage: -
VIN: **1GAZGNFF6H1303553**
Work Order/
Stock Number: **46002075**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G433360U**
Vehicle Grade : **Grade 3.7**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	4.8 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Memory	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 16	Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 13/32 inch	LR Tires - 9/32 inch
RF Tires - 13/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Transforce HT2	Tire Model - RF - Transforce HT2	Tire Model - LR - Transforce HT2
Tire Model - LF - Transforce HT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	3
	Right Qtr Panel	Chipped	-	1
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Rear Cargo Door	Chipped	-	3
	Left Rear Wheel	Corrosion	-	3 To 4 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Hood	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Front Door	Light Scratch	-	4 To 5 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.