



Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 DODGE
DURANGO**
Bodystyle/Series: **4 Door Sport
Utility Vehicle
PURSUIT**
Color: **BLACK**
Mileage: **101,336
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1C4RDJFG7LC308257**
Work Order/
Stock Number: **000310038**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62-6052W**
Vehicle Grade : **Grade 3.4**
Remarks: **-**

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER,
- THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE NONE
- OVER 100K MILES - PRIOR POLICE

Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	No
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	- /BLACK	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Additional Equipment:

Air Conditioning	LF Tires - 4/32 inch	LR Tires - 6/32 inch
Power Brakes	Power Steering	Power Windows
RF Tires - 4/32 inch	RR Tires - 6/32 inch	Security System
Tilt Wheel	Tire Brand - Front Left - LF TIRE MFG Firestone	Tire Brand - Front Right - RF TIRE MFG Firestone
Tire Brand - Rear Left - LR TIRE MFG Firestone	Tire Brand - Rear Right - RR TIRE MFG Firestone	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	Estimate Only	Unknown
[no photo]	Exterior Left	Multiple Scratches Light	Report	Unknown
	Vin Plate	Photo Only	Estimate Only	Unknown
	Floor Panel	Additional Damage	Report	Repair Required
	Frame	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.