



Approved CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE
WAGON**

Color: **WHITE**

Mileage: **39,263
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG3JR324033**

Work Order/
Stock Number: **000381193**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G414134V**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment


Additional Equipment:

3rd Row Seat	4th Passenger Door	ABS Brakes
Air Conditioning	Bluetooth Connection	Brake Assist System
Car Jack	Car Tire Size - RR tire size P225/65SR17	Car Tire Size - LF tire size P225/65SR17
Car Tire Size - LR tire size P225/65SR17	Car Tire Size - RF tire size P225/65SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Dual Air Conditioning	Electrochromic Rearview Mirror
Empty Weight - 4321 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	Hand Tool Kit
Hard Disk Drive Media Storage	Heated Mirrors	Intermittent Wipers
Keyless Entry	LF Tires - 6/32 inch	LR Tires - 8/32 inch
Leather Steering Wheel	MP3 Radio	Master Key - 2key(s)
Motor Fuel Type - Other	OK Odor	Owner's Manual
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 4/32 inch	RR Tires - 8/32 inch
Rear AC	Rear Defrost	Rear Spoiler
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Spare Tire	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg General	Tire Brand - Front Right - RF tire mfg General
Tire Brand - Rear Left - LR tire mfg General	Tire Brand - Rear Right - RR tire mfg General	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission	Trip Computer
Warranty Books	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	Woodgrain Interior Package

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Hood	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Left Front Door	Multiple Dents/No Paint Damage	PDR	2
[no photo]	Left Front Fender	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Left Rear Door	Multiple Dents/No Paint Damage	PDR	2
[no photo]	Right Qtr Panel	Multiple Dents/No Paint Damage	PDR	2
[no photo]	Right Front Door	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Right Front Fender	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Roof	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Right Rear Door	Multiple Dents/No Paint Damage	PDR	2
	Left Qtr Panel	Multiple Dents/Paint Damage	Repair	3
	Liftgate Cladding	Broken	Replace	Replacement Required
	Rear Bumper/Cover	Multiple Scratches Heavy	Repair	3
	Windshield	Star In Glass	Repair	1/2 To 1 Inch
[no photo]	Front Bumper/Cover	Chipped	Touch Up	10 Or More
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.