Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2012 INTERNATIONAL 7000**
Bodystyle/Series:	**- 7600**
Color:	**Silver**
Mileage:	**84,379 (Verified)**
Turn-in Mileage:	-
VIN:	**1HSGRSJR2CJ591984**
Work Order/ Stock Number:	**46209000**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G820202U**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	• paint faded
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**6-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**13 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Air Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 295 / 75 R 22.5	Car Tire Size - LR 295 / 75 R 22.5	Car Tire Size - RR 295 / 75 R 22.5
Car Tire Size - RF 295 / 75 R 22.5	LF Tires - 15/32 inch	LR Tires - 17/32 inch
RF Tires - 17/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - FD663	Tire Model - RF - FS561	Tire Model - LR - FD663
Tire Model - LF - FS561		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Front Wheel	Corrosion	-	4 To 5 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Mud Guard	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Right Front Seat Cushion	Worn	-	Replacement Required
	Left Running Board	Rust	-	7 To 8 Inches
	Hood	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.