



Approved CR

IAA Flint
3088 S. Dye Rd
Branch No 502
Flint, MI 48507
(810)720-0981/(810)732-3518
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 JEEP
GRAND
CHEROKEE**
Bodystyle/Series: **Sport Utility
Vehicle
LAREDO E
4X4**
Color: **Black**
Mileage: **74,167
(Verified)**
Turn-in Mileage: **-**
VIN: **1C4RJFAG0KC544597**
Work Order/
Stock Number: **45948239**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G620607V**
Vehicle Grade : **Grade 3.3**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Power	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 70 R 17

Car Tire Size - LR 245 / 70 R 17

Car Tire Size - RR 245 / 70 R 17

Car Tire Size - RF 245 / 70 R 17

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 6/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - STARFIRE

Tire Brand - Front Right - STARFIRE

Tire Brand - Rear Left - STARFIRE

Tire Brand - Rear Right - STARFIRE


Tire Model - RR - Solarus HT

Tire Model - RF - Solarus HT

Tire Model - LR - Solarus HT

Tire Model - LF - Solarus HT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Cracked	-	> 12 Inches
	Right Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Right Qtr Panel Cladding	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.