Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 CHEVROLET MALIBU**
Bodystyle/Series:	**4 Door Sedan FWD 1FL**
Color:	**Black**
Mileage:	**64,410 (Verified)**
Turn-in Mileage:	-
VIN:	**1G1ZC5ST1LF152737**
Work Order/ Stock Number:	**46436138**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G100989W**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**1.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 205 / 65 R 16	Car Tire Size - LR 205 / 65 R 16	Car Tire Size - RR 205 / 65 R 16
Car Tire Size - RF 205 / 65 R 16	LF Tires - 2/32 inch	LR Tires - 3/32 inch
RF Tires - 6/32 inch	RR Tires - 3/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - SUREDRIVE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - All Season	Tire Model - RF - touring as	Tire Model - LR - All Season
Tire Model - LF - FT140		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Tire	Worn	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required
	Rear Bumper	Heavy Scratch	-	1/2 To 1 Inch
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.