



Approved CR

IAA Sioux Falls  
47028 276th St  
Branch No 362  
Sioux Falls, SD 57104  
(605)271-8855/(605)271-4662  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD  
F-250**  
Bodystyle/Series: **Regular Cab  
XL**  
Color: **Blue**  
Mileage: **49,211  
(Verified)**  
Turn-in Mileage: **-**  
VIN: **1FTBF2B62JEC84062**  
Work Order/  
Stock Number: **46404890**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G632859V**  
Vehicle Grade : **Grade 2.1**  
Remarks: **-**  
Announcements: **-**  
Certification : **-**  
Req. Prev. Repair **-**  
Order:



Drivable: Yes

### Equipment

|                        |                               |                 |                      |
|------------------------|-------------------------------|-----------------|----------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>            |
| Engine:                | <b>8-Cylinder Gas</b>         | Cruise Control: | <b>Yes</b>           |
| Engine Size:           | <b>6.2 L</b>                  | Pwr Steering:   | <b>Yes</b>           |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>           |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>           |
| Interior - Type/Color: | <b>Cloth Interior /GRAY</b>   | Rear Defroster: | <b>No</b>            |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>           |
| Seats:                 | <b>Bench</b>                  | Drive Type:     | <b>4-Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Disc</b>          |

## Equipment

### Additional Equipment:

|                                      |                                      |                                      |
|--------------------------------------|--------------------------------------|--------------------------------------|
| Car Tire Size - LF 245 / 75 R 17     | Car Tire Size - LR 245 / 75 R 17     | Car Tire Size - RR 245 / 75 R 17     |
| Car Tire Size - RF 245 / 75 R 17     | LF Tires - 9/32 inch                 | LR Tires - 9/32 inch                 |
| RF Tires - 9/32 inch                 | RR Tires - 9/32 inch                 | Tire Brand - Front Left - HERCULES   |
| Tire Brand - Front Right - HERCULES  | Tire Brand - Rear Left - HERCULES    | Tire Brand - Rear Right - HERCULES   |
| Tire Model - RR - Terra Trac T/G Max | Tire Model - RF - Terra Trac T/G Max | Tire Model - LR - Terra Trac T/G Max |
| Tire Model - LF - Terra Trac T/G Max |                                      |                                      |

## Non Chargeable Damages

| Photo                                                                               | Item               | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|--------------------|------------|--------|----------|
|    | Instrument Panel   | Photo Only | -      | -        |
|    | Odometer           | Photo Only | -      | -        |
|   | Extra Photo 1      | Photo Only | -      | -        |
|  | Photo - Dash       | Photo Only | -      | -        |
|  | Front Cover Center | Photo Only | -      | -        |
|  | Keys               | Photo Only | -      | -        |
|  | Rear Seats         | Photo Only | -      | -        |
|  | Right Side Panel   | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Left Side Panel         | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|   | Extra Photo 4           | Photo Only | -      | -        |
|  | Extra Photo 5           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Engine                  | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item                   | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|  | Photo - Vin/Id Sticker | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item             | Damage          | Action | Severity             |
|-------------------------------------------------------------------------------------|------------------|-----------------|--------|----------------------|
|    | Right Tail Light | Broken          | -      | Replacement Required |
|    | Hood             | Hail Damage     | -      | 10 Or More           |
|   | Inside Bed       | Previous Repair | -      | Substandard Repair   |
|  | Steering Wheel   | Worn            | -      | Replacement Required |
|  | Cab - Left       | Chipped         | -      | 3                    |

| Chargeable Damages                                                                 |                    |                          |        |             |
|------------------------------------------------------------------------------------|--------------------|--------------------------|--------|-------------|
| Photo                                                                              | Item               | Damage                   | Action | Severity    |
|   | Left Bed Side      | Multiple Scratches Heavy | -      | 10 Or More  |
|   | Right Cab Side     | Multiple Scratches Heavy | -      | 3           |
|   | Right Bed Side     | Multiple Scratches Heavy | -      | 10 Or More  |
|  | Right Front Fender | Dent(S) W/ Paint Dmg     | -      | > 12 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.