Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

| | |
|---|---|
| Make/Model: | **2017 FORD TRANSIT-150** |
| Bodystyle/Series: | **Cargo Van -** |
| Color: | **Green** |
| Mileage: | **24,468 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FTYE1YM9HKB32773** |
| Work Order/ Stock Number: | **46487358** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G433028U** |
| Vehicle Grade : | **Grade 2.5** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |




Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **6-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **3.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **No** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Memory** | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Hydraulic Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - RR 235 / 65 R 16 | Car Tire Size - RF 235 / 65 R 16 | Car Tire Size - LF 235 / 65 R 16 |
| Car Tire Size - LR 235 / 65 R 16 | LF Tires - 7/32 inch | LR Tires - 8/32 inch |
| RF Tires - 7/32 inch | RR Tires - 9/32 inch | Tire Brand - Front Left - HANKOOK |
| Tire Brand - Front Right - HANKOOK | Tire Brand - Rear Left - HANKOOK | Tire Brand - Rear Right - HANKOOK |
| Tire Model - RR - Dynapro HT RH12 (LT-Metric) | Tire Model - RF - Dynapro HT RH12 (LT-Metric) | Tire Model - LR - Dynapro HT RH12 (LT-Metric) |
| Tire Model - LF - Dynapro HT RH12 (LT-Metric) | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Keys | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Side Panel | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Shifter Knob | Worn | - | Replacement Required |
|  | Steering Wheel | Worn | - | Replacement Required |
|  | Left Front Seat Cushion | Stained | - | Permanent |
|  | Right Front Seat Cushion | Stained | - | Permanent |
|  | Right Running Board | Heavy Scratch | - | > 12 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Door | Multiple Scratches Heavy | - | 10 Or More |
|  | Right Rear Door | Heavy Scratch | - | > 12 Inches |
|  | Left Rear Cargo Door | Multiple Scratches Heavy | - | 10 Or More |
|  | Right Rear Cargo Door | Multiple Scratches Heavy | - | 10 Or More |
|  | Left Head Lamp | Faded | - | Repair Required |
|  | Right Head Lamp | Faded | - | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.