Approved CR

IAA Sacramento West
6734 Midway Rd
Branch No 120
Dixon, CA 95620
(707) 640-1240
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 CHEVROLET SILVERADO 2500HD**
Bodystyle/Series:	**Double Cab Truck 4WD STANDARD BED WT**
Color:	**White**
Mileage:	**113,232 (Verified)**
Turn-in Mileage:	-
VIN:	**1GC5YLE75LF268730**
Work Order/ Stock Number:	**46444914**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G630731X**
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LR 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17
Car Tire Size - RR 265 / 70 R 17	LF Tires - 12/32 inch	LR Tires - 10/32 inch
RF Tires - 12/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - BFGOODRICH
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - BFGOODRICH	Tire Brand - Rear Right - BFGOODRICH
Tire Model - LF - All Terrain T/A KO3	Tire Model - LR - All Terrain T/A KO3	Tire Model - RF - All Terrain T/A KO3
Tire Model - RR - All Terrain T/A KO3		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	9 To 10 Inches
	Spoiler	Multiple Scratches Heavy	-	3
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rocker Panel	Multiple Scratches Heavy	-	4
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Tailgate	Multiple Scratches Heavy	-	5
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	-	2
	Right Headlamp Mounting Panel	Multiple Scratches Heavy	-	4
	Left Headlamp Mounting Panel	Chipped	-	3
	Front Metal Bumper Painted	Chipped	-	6
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.