



Approved
CR

IAA Fargo
4401 37th St. N
Branch No 363
Fargo, ND 58102
(701)552-9731/(701)552-9736
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM 3500 CHASSIS**
Bodystyle/Series: **Crew Cab**
TRADESMAN/SLT/LARAMIE
Color: **White**
Mileage: **117,931 (Verified)**
Turn-in Mileage: **-**
VIN: **3C7WRTCJ0JG124971**
Work Order/
Stock Number: **46049982**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G633013U**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 80 R 17

Car Tire Size - RF 235 / 80 R 17

Car Tire Size - LF 235 / 80 R 17

Car Tire Size - LR 235 / 80 R 17

LF Tires - 9/32 inch

LR Tires - 14/32 inch

RF Tires - 8/32 inch

RR Tires - 14/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE



Tire Model - LF - Transforce AT2


Tire Model - LR - Destination X/T

Tire Model - RF - Transforce AT2

Tire Model - RR - Destination X/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Star In Glass	-	1/8 To 1/2 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.