Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD RANGER**
Bodystyle/Series:	**Extended Cab XL**
Color:	**WHITE**
Mileage:	**73,092 (Digital)**
Turn-in Mileage:	-
VIN:	**1FTER1EH5KLA60602**
Work Order/ Stock Number:	**0318708**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G411589W**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• CHECK ENGINE LIGHT. DEFICIENCIES, WHEN KNOWN, • HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER, • THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES • NOT MEAN THERE ARE NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**4-Cylinder Gas Turbo**	Cruise Control:	**No**


Equipment

Engine Size:	**2.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Backup camera and monitor
Bluetooth Connection	Brake Assist System	Car LF Tires - 6/32 inch
Car LR Tires - 6/32 inch	Car RF Tires - 5/32 inch	Car RR Tires - 7/32 inch
Car Tire Size - LF: P255/70SR16 LR: P255/70SR16 RF: P255/70SR16 RR: P255/70SR16 SP: FULL SIZE	Collision Avoidance	Cylinders - 4
Daytime Running Lights	Driver Adjustable Lumbar	Driver Restriction Features
Electronic Stability Control	Engine Immobilizer	Forward Collision Alert System
Front Head Air Bag	Ignition Key - 1key(s)	Intermittent Wipers
LF Tires - 6/32 inch	LR Tires - 6/32 inch	MP3 Radio
Pass. Air Bag	Passenger Adjustable Lumbar	Passenger Air Bag Sensor
RF Tires - 5/32 inch	RR Tires - 7/32 inch	Rear Head Air Bag
Side Airbags - Front	Smart Device Integration	Spare Tire - Full Size
Spare Wheel - Steel	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tire Brand - Front Left - OTHER	Tire Brand - Front Right - OTHER
Tire Brand - Rear Left - OTHER	Tire Brand - Rear Right - OTHER	Tire LF - 6/32 inch
Tire Pressure Monitor System	Tire RF - 5/32 inch	Tire Size - LF: P255/70SR16 LR: P255/70SR16 RF: P255/70SR16 RR: P255/70SR16 SP: FULL SIZE
Tire Size - LF: P255/70SR16 LR: P255/70SR16 RF: P255/70SR16 RR: P255/70SR16 SP: FULL SIZE	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel	WiFi Hotspot	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Rust	Repair	10 To 11 Inches
	Left Front Door	Previous Repair	Light Compound	Buffable
	Left Front Door Edge	Bent	Repair	1 To 2 Inches
	Left Front Fender	Previous Repair	Light Compound	Buffable
	Left Bed Side	Previous Repair	Light Compound	Buffable
	Left Rear Door	Previous Repair	Light Compound	Buffable
	Rear Bumper/Cover	Multiple Scratches Heavy	Refinish	10 Or More
	Gas Cap	Missing	Replace	Replacement Required
	Tailgate Protective Cap	Hole(S)	Replace	Replacement Required
	Right Rear Door	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
	Right Front Door Edge	Multiple Scratches Heavy	Repair	10 Or More
	Roof	Multiple Dents/Paint Damage	Repair	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Center Armrest	Aftermarket	Replace	Replacement Required
	Left Front Seat Cushion	Worn	Replace	Replacement Required
	Steering Wheel	Worn	Replace	Replacement Required
	Warning Light - Engine	On	Mechanical Check	Unacceptable
	Video Screen	Hole(S)	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.