



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-150**
Bodystyle/Series: **Cargo Van -**
Color: **Green**
Mileage: **26,874
(Verified)**
Turn-in Mileage: **-**
VIN: **1FTYE1ZM2JKB42419**
Work Order/
Stock Number: **46396269**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G431560V**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Memory	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

LF Tires - 8/32 inch

LR Tires - 8/32 inch

RF Tires - 7/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - Wrangler Workhorse HT C-Type

Tire Model - RF - Wrangler Workhorse HT C-Type

Tire Model - LR - Wrangler Workhorse HT C-Type

Tire Model - LF - Wrangler Workhorse HT C-Type

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Cargo Shelf	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rocker Panel Molding	Missing	-	Replacement Required
	Left Rear Cargo Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Rear Cargo Door	Dent(S) W/ Paint Dmg	-	8 To 9 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper Left Molding	Dent(S) W/ Paint Dmg	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Drip Rail	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.