



Approved CR

IAA Billings
75 Cerise Road
Branch No 361
Billings, MT 59101
(406) 259-2377/(406) 259-2302
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 RAM
1500
CLASSIC
Crew Cab**
Bodystyle/Series: **TRADESMAN
4X4 5'7 BOX**
Color: **Gray**
Mileage: **94,988
(Verified)**
Turn-in Mileage: **-**
VIN: **3C6RR7KT5MG663957**
Work Order/
Stock Number: **46329200**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G627020Y**
Vehicle Grade : **Grade 3.2**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17
Car Tire Size - RR 265 / 70 R 17	LF Tires - 9/32 inch	LR Tires - 10/32 inch
RF Tires - 9/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Workhorse At	Tire Model - LR - Wrangler Workhorse At	Tire Model - RF - Wrangler Workhorse At
Tire Model - RR - Wrangler Workhorse At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Rear Door Panel	Multiple Scratches Light	-	5
	Left Rear Door Panel	Multiple Scratches Light	-	4
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	-	2
	Right Front Wheel	Corrosion	-	1 To 2 Inches
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Heavy Scratch	-	> 12 Inches
	Left Front Wheel	Corrosion	-	9 To 10 Inches
	Left Drip Rail	Chipped	-	3
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Hood	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.