Approved CR

IAA Santa Clarita
14320 Soledad Canyon Rd
Branch No 128
Santa Clarita, CA 91387
(818) 655-0279/(224) 348-4123
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle LS**
Color:	**Black**
Mileage:	**1,752 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSCAEC4JR323917**
Work Order/ Stock Number:	**46408348**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G422167U**
Vehicle Grade :	**Grade 4.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment



Additional Equipment:

Car Tire Size - LF 265 / 65 R 18	Car Tire Size - LR 265 / 65 R 18	Car Tire Size - RR 265 / 65 R 18
Car Tire Size - RF 265 / 65 R 18	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RR - Energy Saver A/S	Tire Model - RF - Energy Saver A/S	Tire Model - LR - Energy Saver A/S
Tire Model - LF - Energy Saver A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hitchplate Cover	Missing	-	Replacement Required
	Right Front Fender	Chipped	-	3
	Front Bumper	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.