



Approved
CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD F-150**
Bodystyle/Series: **Crew Cab XL**
Color: **Blue**
Mileage: **58,068 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTEW1E84HKD49672**
Work Order/
Stock Number: **46325685**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G621759U**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements:

• ANNOUNCEMENTS:
Rust

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 3/32 inch	LR Tires - 4/32 inch
RF Tires - 13/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - ROYAL BLACK	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - ROYAL BLACK
Tire Model - LF - Wrangler Fortitude HT	Tire Model - LR - Wrangler Fortitude HT	Tire Model - RF - milagemax ltr
Tire Model - RR - milagemax ltr		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Worn	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Cab - Left	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Left Head Lamp	Faded	-	Repair Required
	Front Metal Bumper Painted	Rust	-	5 To 6 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Rust	-	Repair Required
	Right Rear Wheel	Rust	-	Repair Required
	Tailgate	Heavy Scratch	-	1/8 To 1/2 Inch
	Left Rear Wheel	Rust	-	Repair Required
	Left Front Wheel	Rust	-	Repair Required
	Left Bed Side	Heavy Scratch	-	< 1/8 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.