



Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
SILVERADO
1500**
Bodystyle/Series: **- WT**
Color: **White**
Mileage: **50,385
(Verified)**
Turn-in Mileage: **-**
VIN: **1GCVKNEH3HZ305687**
Work Order/
Stock Number: **46368594**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G620902U**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 7/32 inch	LR Tires - 8/32 inch
RF Tires - 7/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler Workhorse RT	Tire Model - RF - Wrangler Workhorse RT	Tire Model - LR - Wrangler Workhorse RT
Tire Model - LF - Wrangler Workhorse At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Tonneau Cover	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Shelf	Aftermarket	-	Acceptable
	Odometer	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Front Metal Bumper Painted	Chipped	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Left Rear Wheel	Corrosion	-	1/2 To 1 Inch
	Left Bed Side	Heavy Scratch	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.