



Approved CR

IAA Fort Worth-North
3748 McPherson Dr
Branch No 465
Justin, TX 76247
(940) 648-5541/(940) 648-5543
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
DURANGO**
Bodystyle/Series: **Sport Utility
Vehicle SXT
AWD**
Color: **Black**
Mileage: **91,371
(Verified)**
Turn-in Mileage: **-**
VIN: **1C4RDJAG8KC744430**
Work Order/
Stock Number: **46368368**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G611586W**
Vehicle Grade : **Grade 3.0**
Remarks: **-**
Announcements:

- Active Codes
see IAA
Condition
Report

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /TAN	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes


Equipment

Additional Equipment:

Car Tire Size - RR 265 / 60 R 18	Car Tire Size - RF 265 / 60 R 18	Car Tire Size - LF 265 / 60 R 18
Car Tire Size - LR 265 / 60 R 18	LF Tires - 4/32 inch	LR Tires - 7/32 inch
RF Tires - 3/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler At/S	Tire Model - LR - Wrangler At/S	Tire Model - RF - Wrangler At/S
Tire Model - RR - Wrangler At/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Hail Damage	-	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	2
	Front Bumper	Chipped	-	1
	Hood	Hail Damage	-	10 Or More
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.