



Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
SILVERADO
3500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Black**

Mileage: **35,574
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC4KYCG0HF187655**

Work Order/
Stock Number: **46364619**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630269U**

Vehicle Grade : **Grade 1.9**

Remarks: **-**

Announcements:

**• HAIL
DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment



Additional Equipment:

Car Tire Size - LF 265 / 70 R 18	Car Tire Size - LR 265 / 70 R 18	Car Tire Size - RR 265 / 70 R 18
Car Tire Size - RF 265 / 70 R 18	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 13/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - DYNAMO	Tire Brand - Rear Left - DYNAMO	Tire Brand - Rear Right - DYNAMO
Tire Model - LF - Dynapro AT2 RF11	Tire Model - RR - Dynapro At RF08	Tire Model - RF - Dynapro At RF08
Tire Model - LR - Dynapro At RF08		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Hood	Hail Damage	-	10 Or More
	Tailgate	Chipped	-	10 Or More
	Right Rear Door	Chipped	-	10 Or More
	Right Front Door	Heavy Scratch	-	3 To 4 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Bed Side	Chipped	-	3
	Left Bed Side	Hail Damage	-	3
	Left Front Fender	Hail Damage	-	10 Or More
	Roof	Hail Damage	-	10 Or More
	Left Drip Rail	Hail Damage	-	10 Or More
	Right Front Fender	Hail Damage	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.