



Approved CR

IAA Albuquerque
4400 Broadway Blvd SE
Branch No 140
Albuquerque, NM 87105
(505) 873-2081/(505) 873-3029
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FOCUS**
Bodystyle/Series: **4 Door Sedan
SE**
Color: **Silver**
Mileage: **40,448
(Verified)**
Turn-in Mileage: **-**
VIN: **1FADP3F25JL327300**
Work Order/
Stock Number: **46318400**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G13-1491V**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Drum

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 55 R 16	Car Tire Size - RF 215 / 55 R 16	Car Tire Size - LF 215 / 55 R 16
Car Tire Size - LR 215 / 55 R 16	LF Tires - 5/32 inch	LR Tires - 5/32 inch
RF Tires - 5/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - LF - Contiprocontact	Tire Model - LR - Contiprocontact	Tire Model - RF - Contiprocontact
Tire Model - RR - Contiprocontact		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Heavy Scratch	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.