Approved CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 2500**
	-
Bodystyle/Series:	**TRADESMAN 4X4 8` BOX**
Color:	**Red**
Mileage:	**61,486 (Verified)**
Turn-in Mileage:	-
VIN:	**3C6LR5AT8JG363594**
Work Order/ Stock Number:	**46480196**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G633412V**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	• Warning indicator on • repairs may be needed
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 70 R 18	Car Tire Size - LR 275 / 70 R 18	Car Tire Size - RR 275 / 70 R 18
Car Tire Size - RF 275 / 70 R 18	LF Tires - 10/32 inch	LR Tires - 9/32 inch
RF Tires - 10/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler All-Terrain Adventure With Kevl	Tire Model - RF - Wrangler All-Terrain Adventure With Kevl	Tire Model - LR - Wrangler All-Terrain Adventure With Kevl
Tire Model - LF - Wrangler All-Terrain Adventure With Kevl		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Chipped	-	3
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	6 To 7 Inches
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.