



Approved
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM 1500**
Bodystyle/Series: **- TRADESMAN 4X4
6'4 BOX**
Color: **Gray**
Mileage: **55,478 (Verified)**
Turn-in Mileage: **-**
VIN: **1C6RR7FG1JS291499**
Work Order/
Stock Number: **46414593**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G621649V**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements:

**• ANNOUNCEMENTS:
Corrosion**

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Synthetic Leather /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 65 R 17

Car Tire Size - RF 265 / 65 R 17

Car Tire Size - LF 265 / 65 R 17

Car Tire Size - LR 265 / 65 R 17

LF Tires - 11/32 inch

LR Tires - 10/32 inch

RF Tires - 11/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Destination LE2

Tire Model - RF - Destination LE2

Tire Model - LR - Destination LE2

Tire Model - LF - Destination LE2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Front Door Panel	Multiple Scratches Light	-	5
	Left Rear Door Panel	Multiple Scratches Light	-	5
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	4
	Hood	Chipped	-	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	1 To 2 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Bed Side	Multiple Scratches Light	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	3 To 4 Inches
	Lf Mirror Cover	Multiple Scratches Light	-	3
	Left Front Fender	Chipped	-	5
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Left Rear Door	Multiple Scratches Light	-	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.