



Approved CR

IAA Charleston
430 Tannenbaum Rd
Branch No 720
Ravenel, SC 29470
(843) 556-7620/(843) 571-3006
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
CHARGER**
4 Door Sedan
Bodystyle/Series: **POLICE
RWD**
Color: **Silver**
Mileage: **75,338
(Verified)**
Turn-in Mileage: -
VIN: **2C3CDXAG9KH513207**
Work Order/
Stock Number: **46414836**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G111313V**
Vehicle Grade : **Grade 4.0**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 60 R 18	Car Tire Size - LF 225 / 60 R 18	Car Tire Size - RF 225 / 60 R 18
Car Tire Size - LR 225 / 60 R 18	LF Tires - 8/32 inch	LR Tires - 5/32 inch
RF Tires - 8/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - KELLY
Tire Brand - Front Right - KELLY	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire Model - RR - Edge Touring A/S	Tire Model - RF - Edge Touring A/S	Tire Model - LR - Edge Touring A/S
Tire Model - LF - Edge Touring A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Cargo Shelf	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Front Wheel Cover	Peeling	-	1 To 2 Inches
	Rf Mirror Cover	Multiple Scratches Heavy	-	3
	Left Front Wheel Cover	Peeling	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	2
	Left Rear Wheel Cover	Peeling	-	> 12 Inches
	Rear Bumper	Multiple Scratches Heavy	-	2
	Right Rear Wheel Cover	Curb Rash	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.