



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
EXPRESS
2500**
Bodystyle/Series: **Van LS**
Color: **Black**
Mileage: **32,573
(Verified)**
Turn-in Mileage: -
VIN: **1GNWGEFG8H1301670**
Work Order/
Stock Number: **46366129**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G422356U**
Vehicle Grade : **Grade 3.3**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /BROWN	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Memory	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16

Car Tire Size - RF 245 / 75 R 16

Car Tire Size - LF 245 / 75 R 16

Car Tire Size - LR 245 / 75 R 16

LF Tires - 9/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - ARROYO

Tire Brand - Front Right - ARROYO

Tire Brand - Rear Left - ARROYO

Tire Brand - Rear Right - ARROYO

Tire Model - LF - Eco Pro H/T

Tire Model - LR - Eco Pro H/T

Tire Model - RF - Eco Pro H/T

Tire Model - RR - Eco Pro H/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Front Bumper Cover Upper	Heavy Scratch	-	2 To 3 Inches
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Right Front Door	Heavy Scratch	-	1/8 To 1/2 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Heavy Scratch	-	1/8 To 1/2 Inch
	Right Qtr Panel	Heavy Scratch	-	1/8 To 1/2 Inch
	Rear Bumper Step Pad	Gouged	-	1/8 To 1/2 Inch
	Rear Ls Panel Extension	Multiple Scratches Heavy	-	4
	Left Side Panel	Heavy Scratch	-	5 To 6 Inches
	Left Rear Cargo Door	Chipped	-	1

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.