



Approved CR

IAA Tucson
4650 E Irvington Rd
Branch No 424
Tucson, AZ 85714
(520) 319-9393 / (520) 519-9491
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
SUBURBAN**

Bodystyle/Series: **Sport Utility
Vehicle LS**

Color: **White**

Mileage: **47,478
(Verified)**

Turn-in Mileage: **-**

VIN: **1GNSKGEC8JR323621**

Work Order/
Stock Number: **46359900**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G622753V**

Vehicle Grade : **Grade 3.9**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 65 R 18	Car Tire Size - LR 265 / 65 R 18	Car Tire Size - RR 265 / 65 R 18
Car Tire Size - RF 265 / 65 R 18	LF Tires - 10/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RR - Defender LTX M/S 2	Tire Model - RF - Defender LTX M/S 2	Tire Model - LR - Defender LTX M/S 2
Tire Model - LF - Defender LTX M/S 2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	10 Or More
	Hood	Chipped	-	6
	Right Front Wheel	Curb Rash	-	2 To 3 Inches
	Right Rear Door	Chipped	-	2
	Hitchplate Cover	Missing	-	Replacement Required
	Lift Gate	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.