Approved
CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 RAM 4500 CHASSIS**
Bodystyle/Series:	**Crew Cab TRADESMAN/SLT/LARAMIE**
Color:	**Black**
Mileage:	**83,035 (Verified)**
Turn-in Mileage:	-
VIN:	**3C7WRLEJ9GG156467**
Work Order/ Stock Number:	**46461007**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710512R**
Vehicle Grade :	**Grade 1.8**
Remarks:	-
Announcements:	• CONDITION UNKNOWN • LIFT GATE MAY NEED REPAIRS OR REPLACEMENT
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 70 R 19.5	Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LF 225 / 70 R 19.5
Car Tire Size - LR 225 / 70 R 19.5	LF Tires - 13/32 inch	LR Tires - 14/32 inch
RF Tires - 12/32 inch	RR Tires - 15/32 inch	Tire Brand - Front Left - ADVANCE
Tire Brand - Front Right - ADVANCE	Tire Brand - Rear Left - ADVANCE	Tire Brand - Rear Right - ADVANCE
Tire Model - LF - GR-A1 Series	Tire Model - LR - GR-A1 Series	Tire Model - RF - GR-A1 Series
Tire Model - RR - GR-A1 Series		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Right Front Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Multiple Scratches Heavy	-	10 Or More
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Tailgate	Rust	-	> 12 Inches
	Left Side Panel	Multiple Scratches Heavy	-	10 Or More
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Cab - Left	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches
	Right Cab Side	Multiple Scratches Heavy	-	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.