



Approved
CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 RAM 5500
CHASSIS**

Bodystyle/Series: **-
TRADESMAN/SLT**

Color: **White**

Mileage: **67,423 (Verified)**

Turn-in Mileage: **-**

VIN: **3C7WRNBJ6FG706187**

Work Order/
Stock Number: **46276977**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G710672S**

Vehicle Grade : **Grade 2.1**

Remarks: **-**

Announcements: **• HAIL DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19

Car Tire Size - LR 225 / 70 R 19

Car Tire Size - RR 225 / 70 R 19

Car Tire Size - RF 225 / 70 R 19

LF Tires - 10/32 inch

LR Tires - 11/32 inch

RF Tires - 11/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - KELLY

Tire Brand - Front Right - KELLY

Tire Brand - Rear Left - KELLY

Tire Brand - Rear Right - KELLY

Tire Model - RR - Armorsteel RSD

Tire Model - RF - Armorsteel RSD


Tire Model - LR - Armorsteel RSD

Tire Model - LF - Armorsteel RSD

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Odometer	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Hail Damage	-	10 Or More
	Tailgate	Rust	-	> 12 Inches
	Grille	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Hail Damage	-	5
	Hood	Hail Damage	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.