



Approved
CR

IAA Southern NJ
250 Blackwood-Barnsboro Road
Branch No 612
Turnersville, NJ 08012
(856) 227-8760/(856) 227-8943
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
3500**
Bodystyle/Series: **Crew Cab
TRADESMAN**
Color: **Black**
Mileage: **54,836
(Verified)**
Turn-in Mileage: **-**
VIN: **3C63R3GL3GG374233**
Work Order/
Stock Number: **46411667**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632597S**
Vehicle Grade : **Grade 3.4**
Remarks: **-**
Announcements:

- repairs may be needed
- Warning indicator on

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 275 / 70 R 18

Car Tire Size - RF 275 / 70 R 18

Car Tire Size - LF 275 / 70 R 18

Car Tire Size - LR 275 / 70 R 18

LF Tires - 10/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Transforce A/T

Tire Model - LR - Transforce A/T

Tire Model - RF - Transforce A/T

Tire Model - RR - Transforce A/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Traction Control	On	-	Unacceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Hardtop Shell	Multiple Dents/Paint Damage	-	10 Or More
	Rear Metal Bumper Painted	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.