



Approved CR

IAA Charleston
430 Tannenbaum Rd
Branch No 720
Ravenel, SC 29470
(843) 556-7620/(843) 571-3006
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION
HYBRID**

Bodystyle/Series: **4 Door Sedan
S**

Color: **Black**

Mileage: **43,109
(Verified)**

Turn-in Mileage: **-**

VIN: **3FA6P0UU2JR243626**

Work Order/
Stock Number: **46411437**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G101937V**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17

Car Tire Size - RR 225 / 50 R 17

Car Tire Size - LR 225 / 50 R 17

Car Tire Size - RF 225 / 50 R 17

LF Tires - 8/32 inch

LR Tires - 9/32 inch

RF Tires - 8/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - UNIROYAL

Tire Brand - Front Right - UNIROYAL

Tire Brand - Rear Left - UNIROYAL

Tire Brand - Rear Right - UNIROYAL

Tire Model - LF - Tiger Paw XTM

Tire Model - LR - Tiger Paw XTM

Tire Model - RF - Tiger Paw XTM

Tire Model - RR - Tiger Paw XTM

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Led Flashlight	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Rear Wheel	Curb Rash	-	1 To 2 Inches
	Deck Lid	Chipped	-	3
	Left Qtr Panel	Chipped	-	3
	Left Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Front Wheel	Curb Rash	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.