



Approved CR

IAA Birmingham
1600 Highway 150
Branch No 727
Bessemer, AL 35022
(205) 426-2300/(205) 428-5332
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **Blue**

Mileage: **53,098
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPD74LF5LH616238**

Work Order/
Stock Number: **46379480**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G131766X**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 5	Car Tire Size - LR 195 / 65 R 5	Car Tire Size - RR 195 / 65 R 5
Car Tire Size - RF 195 / 65 R 5	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 9/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - RR - Kinergy GT H436	Tire Model - RF - Kinergy GT H436	Tire Model - LR - Kinergy GT H436
Tire Model - LF - Kinergy GT H436		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Heavy Scratch	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rocker Panel	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Rear Bumper	Scuffed	-	> 12 Inches
	Front Bumper	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.