



Approved
CR

IAA Billings
75 Cerise Road
Branch No 361
Billings, MT 59101
(406) 259-2377/(406) 259-2302
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 SUBARU ASCENT**
Sport Utility Vehicle
Bodystyle/Series: **PREMIUM 8-PASSENGER**
Color: **Gray**
Mileage: **170,164 (Verified)**
Turn-in Mileage: -
VIN: **4S4WMABD6P3407135**
Work Order/
Stock Number: **45778078**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G622337Z**
Vehicle Grade : **Grade 3.2**
Remarks: -
Announcements:

• WARNING
LIGHTS ON

Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 60 R 18

Car Tire Size - LR 245 / 60 R 18

Car Tire Size - RR 245 / 60 R 18

Car Tire Size - RF 245 / 60 R 18

LF Tires - 8/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - COOPER

Tire Brand - Front Right - COOPER

Tire Brand - Rear Left - COOPER

Tire Brand - Rear Right - COOPER

Tire Model - RR - Discoverer Road + Trail
At

Tire Model - RF - Discoverer Road + Trail
At


Tire Model - LR - Discoverer Road + Trail
At

Tire Model - LF - Discoverer Road + Trail
At

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Blind Spot Monitor	On	-	Unacceptable
	Warning - Collision Avoidance	On	-	Unacceptable
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	8
	Hood	Chipped	-	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Left Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Rear Bumper	Dent(S) W/ Paint Dmg	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.