



Approved CR

IAA Sacramento
11499 Dougals Road
Branch No 331
Rancho Cordova, CA 95742
(916) 635-4271/(916) 635-1637
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 JEEP
CHEROKEE**
Bodystyle/Series: **Sport Utility
Vehicle
LATITUDE
4X4**
Color: **Black**
Mileage: **46,609
(Verified)**
Turn-in Mileage: **-**
VIN: **1C4PJMCB2JD580989**
Work Order/
Stock Number: **46305915**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G612569U**
Vehicle Grade : **Grade 4.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 12/32 inch	LR Tires - 12/32 inch
RF Tires - 12/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - MAZAMA
Tire Brand - Front Right - MAZAMA	Tire Brand - Rear Left - MAZAMA	Tire Brand - Rear Right - MAZAMA
Tire Model - LF - Open Range HTS	Tire Model - LR - Open Range HTS	Tire Model - RF - Open Range HTS
Tire Model - RR - Open Range HTS		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/No Paint Dmg	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.