



Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
SILVERADO
2500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Silver**

Mileage: **34,548
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEG8JF236356**

Work Order/
Stock Number: **46305502**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630504V**

Vehicle Grade : **Grade 2.0**

Remarks: **-**

Announcements:

- WARNING INDICATOR LIGHT ON (SEE IAA CONDITION REPORT FOR DETAILS)

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather/Cloth Interior /GRAY	Rear Defroster:	No

Equipment

Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc
Additional Equipment:			
Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17	
Car Tire Size - RF 245 / 75 R 17	LF Tires - 15/32 inch	LR Tires - 16/32 inch	
RF Tires - 15/32 inch	RR Tires - 16/32 inch	Tire Brand - Front Left - MAZAMA	
Tire Brand - Front Right - MAZAMA	Tire Brand - Rear Left - MAZAMA	Tire Brand - Rear Right - MAZAMA	
Tire Model - RR - Open Range A/T Plus	Tire Model - RF - Open Range A/T Plus	Tire Model - LR - Open Range A/T Plus	
Tire Model - LF - Open Range A/T Plus			

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	7 To 8 Inches
	Right Front Door	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Bed Side	Multiple Dents/Paint Damage	-	4
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	-	5
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Door	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Rocker Panel	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Left Front Seat Cushion	Torn	-	3 To 4 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.